PCT/DE 00/02210

5		List of reference signs
	1	Endless sieve belt
	2, 2', 2''	Sieving panels
	3	Connectors
10	4	Center guide
10	5	Outer wall
	6	Guide
	7a	Exterior guide roller
	7b	Interior guide roller
15	8, 8'	Connecting rods
	9	Mounting plate
	10	Articulated joint
	11	Support roller
	12a	Upper sprocket wheel
20	12b	Lower sprocket wheel
	13	Sieve belt strut
	14	Drive shaft
	15	Drive motor
	16	Indentation
25	17	Spray head
	18	Spray jet
	19	Debris channel
	20	Liquid current
	21	Cover
30	22	Sluice channel
	23	Direction of motion (of 1)
	24	Sectional frame
	25	Sieving element
	26	First, convex section
35	27	Second, concave section

	28	Drive chain
	29	Debris pocket
	30	Beveling
	31	Structure
5	32	Guide groove
	33	Guide section
	34	Clean water side
	35	Wastewater side
	36	Chamfering
10	37	Cross-bar
	38	Connecting section